






## Photo Instructions






**7 Axle**















Make sure to tuck L Motor cables where circled










Make sure to put grey axle through Bush









































Run cables through space where circles are, try to get cables as close as you can to this picture







Try to keep cables away from gears on right side













































































Figure 8 loop with light cable around 5 axles






























**Finished!**